



Connector plates – Large & Ultimate

READ General Instructions FIRST!

TIP: Most pieces fit together without glue. Do a test run first, before gluing.

Sheets:

Large: LK-03

Ultimate: LK-03, UDA-2 or UGA-2

1



1 the pieces to be glued.

2



2 glue the two little T-shaped pieces into the small slits.

Ultimate only: Dropper: UDS-1, UDS-2 | GW: UGS-1, UGS-2

3



3 the pieces to be glued.

4





4 glue the four little T-shaped pieces into the small cutouts.

5



5 glue the two pieces on top of each other, along the line cut into them, the tabs sticking out to the same side as the second plate. Ensure right angles.



The "Bones" are to connect units to each other. No glue.

These plates are to connect the lower drawers and low paint element to each other and / or the large stepped paint units. The Ultimate only connector is only to have a low large paint element connected centrally to the two work areas. See setup guide for details.