

Connector plates – Large & Ultimate

READ General Instructions FIRST!

TIP: Most pieces fit together without glue. Do a test run first, before gluing.

Sheets:

Large: LK-03

Ultimate: LK-03, UDA-2 or UGA-2

I




1 the
pieces to
be glued.



2 glue the two little T-shaped pieces into the small slits.

These plates are to connect the lower drawers and low paint element to each other and / or the large stepped paint units. The Ultimate only connector is only to have a low large paint element connected centrally to the two work areas. See setup guide for details.



**The “Bones”
are to
connect units
to each other.
No glue.**

Ultimate only: Dropper: UDS-1, UDS-2 | GW: UGS-1, UGS-2

3



3 the
pieces to
be glued.

4



4 glue the four little T-shaped pieces into the small cutouts.

5



5 glue the two pieces on top of each other, along the line cut into them, the tabs sticking out to the same side as the second plate. Ensure right angles.